Request for Certificate of Correction dated June 12, 2006

Atty. Docket: MUCC-87

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 CFR §1.322 (a)) AND APPLICANTS' MISTAKE (37 C.F.R. §1.323)

Attached is Form PTO-1050, which is suitable for printing.

Many of the errors below are (or may be contended to be) the mistake of Applicants, who state that the errors are of a minor nature in character and occurred in good faith, and correction thereof does not involve such changes in the patent as would constitute new matter or would require reexamination. Some of the errors that appear in Form PTO-1050 were typographical errors, which occurred through the fault of the U.S. Patent and Trademark Office ("PTO").

The exact column and line number where the errors are shown in the patent are as follows:

Cover page, column 2, line approx. 18 reads "containers are" and should read -- containers and are -- .

Cover page, column 2, line approx. 21 reads "0.008 inches" and should read -- 0.008 inch --.

Cover page, column 2, line approx. 31 reads "indicia, because, in" and should read -- indicia, in --.

Cover page, column 2, line approx. 32 reads "themselves, are protected" and should read --themselves, and thus are protected --.

Column 1, line 16 reads "so as make" and should read -- so as to make --.

Column 1, line approx, 43 reads "teach that" and should read -- teach --.

Column 1, line approx. 48 reads "0.008 inches" and should read -- 0.008 inch --.

Column 3, line approx. 33 reads "0.008 inches" and should read -- 0.008 inch --.

Column 3, line approx. 57 reads "contemplates, a" and should read -- contemplates a --.

U.S. Application Serial No. 09/888,121

U.S. Patent No. 6,991,261

Request for Certificate of Correction dated June 9, 2006

Atty. Docket: MUCC-87

Column 4, line approx. 20 reads "0.008 inches" and should read -- 0.008 inch --.

Column 6, line approx. 46 reads "0.0024-0.0038 inches" and should read -- 0.0024-0.0038 inch --.

Column 6, line approx. 48 reads "MD, TD" and should read -- MD, TD* --.

Column 6, line 65 reads "Before (if reverse printing is employed), applying" and should read -- Before (if reverse printing is employed) applying --.

Column 8, line approx. 9 reads "Presently preferred, is" and should read -- Presently preferred is --.

Column 9, line approx. 52 reads "0.008 inches" and should read -- 0.008 inch --.

Column 10, line approx. 45 reads "0.008 inches" and should read -- 0.008 inch --.

A fee of \$100.00 is believed due as a result of this Request. Any deficiencies or credits necessary to complete this communication should be applied to Deposit Account No. 23-3000.

Respectfully submitted, WOOD, HERRON & EVANS, L.L.P.

By: /David E. Jefferies/
David E. Jefferies, Reg. No. 46,800